



743 Iona Rd. Idaho Falls, ID 83401, (208)529-0244 Fax (208)529-9000

## Important Technical Update

### Models - 2005/2006 Polaris RMK 900 2006 Polaris RMK 700

**Condition:** Air leaks in the belly pan seams allow powder snow to enter the under hood area.

**Correction:** Run a bead of silicone down the seams in the belly pan as well as the seam where the bumper and belly pan come together (see illustration below). NOTE: Make sure to seal the area where the belly pan and bumper come together around the nose of the sled.

